

TREE CONDITION DATA SUMMARY

I. Summary of Field Data for Green Lake Park (All Zones)

Tree Hazard Conditions and Abatement Recommendations:
(Total Number of Trees in each Category)

- 24 Removal / High Hazard Potential
- 113 Prune Defective Parts
- 89 Removal / Low Hazard Potential
- 64 'Watch' Status (Further inspection required)

II. Summaries of Field Data by Subareas Community Center - CC

Tree Hazard Conditions and Abatement Recommendations:
(Total Number of Trees in each Category)

- 4 Removal / High Hazard Potential
- 37 Prune Defective Parts
- 14 Removal / Low Hazard Potential
- 8 'Watch' Status (Further inspection required)

Wading Pool - WP

Tree Hazard Conditions and Abatement Recommendations:
(Total Number of Trees in each Category)

- 4 Removal / High Hazard Potential
- 22 Prune Defective Parts
- 14 Removal / Low Hazard Potential
- 10 'Watch' Status (Further inspection required)

TREE CONDITION DATA SUMMARY

I. Summaries of Field Data by Subareas (cont.)

Bathhouse - BH

Tree Hazard Conditions and Abatement Recommendations:
(Total Number of Trees in each Category)

 5 Removal / High Hazard Potential

 15 Prune Defective Parts

 32 Removal / Low Hazard Potential

 14 Watch' Status (Further inspection required)

Aurora Strip - AS

Tree Hazard Conditions and Abatement Recommendations:
(Total Number of Trees in each Category)

 0 Removal / High Hazard Potential

 6 Prune Defective Parts

 3 Removal / Low Hazard Potential

 6 Watch' Status (Further inspection required)

Aqua Center / Pitch and Putt - AC / PP

Tree Hazard Conditions and Abatement Recommendations:
(Total Number of Trees in each Category)

 4 Removal / High Hazard Potential

 26 Prune Defective Parts

 16 Removal / Low Hazard Potential

 3 Watch' Status (Further inspection required)

TREE CONDITION DATA SUMMARY

II. Summaries of Field Data by Subareas (cont.) **Southeast Shore - SS**

Tree Hazard Conditions and Abatement Recommendations:
(Total Number of Trees in each Category)

- 7 Removal / High Hazard Potential
- 7 Prune Defective Parts
- 10 Removal / Low Hazard Potential
- 23 Watch' Status (Further inspection required)

SOURCE: Kathleen Day (June 1995)